

# Addendum No. 1

---

**Date:** 09.07.2017

**Re:** **Prairie Centre Buildings E & F2, St Charles**  
NHA No.2017.03.00

This addendum forms part of the Contract Documents and modifies the original Bidding Documents dated 07.18.2017 and Permit Revision documents dated 09.07.2017 as noted below. Bidders shall acknowledge receipt of this Addendum in the space provided on the Bid Form (Failure to do so may subject Bidder to disqualification).

This Addendum consists of 23 drawing sheet(s).

## Changes and Clarifications to the Drawing Set:

Item #	Description	Drawing(s)/ Detail(s) Referenced	Attachment (# of pages)
1	Dimension updated	A106	1
2	Stair riser height clarified.	A305	1
3	R value added to typical wall information.	A501	1
4	Revised delegated engineer requirement in Steel and Wood structural notes.	S001	1
5	Editorial corrections to plan keynotes. Corrected erroneous section cut indications. Corrected keynote indications on plan.	S100a	1
6	Clarified top of wall step conditions. Corrected top of wall elevation at Stair S-01. Removed erroneous beam bearing pocket indication. Revised plan keynotes.	S100b	1
7	Editorial corrections to plan keynotes. Corrected erroneous section cut indications. Corrected keynote indications on plan.	S101a	1
8	Corrected Section cut indications at Stair S-01.	S101b	1
9	Added elevator wall stud keynote to partial plan. Corrected notes in details J11 and N11	S102	1
10	Corrected plan keynotes. Revised detail cuts on plan as indicated. Revised plan at Stair S-01. Added opening and lintel indication at	S103	1

	Stair S-02. Added lintel indication in exterior wall adjacent to K1. Corrected detail callout in Section J.		
11	Corrected plan keynotes. Revised detail cuts on plan as indicated. Added missing lintel sizes.	S104	1
12	Editorial corrections to plan keynotes. Corrected erroneous section cut indications. Corrected keynote indications on plan.	S105a	1
13	Clarified top of wall step conditions. Corrected top of wall elevation at Stair S-01. Removed erroneous beam bearing pocket indication. Revised plan keynotes.	S105b	1
14	Editorial corrections to plan keynotes. Corrected erroneous section cut indications. Corrected keynote indications on plan.	S106a	1
15	Added HSS tag and corrected keynote at column line D. Corrected Section cut indications at Stair S-01.	S106b	1
16	Corrected plan keynotes. Revised detail cuts on plan as indicated. Added missing lintel sizes. Corrected notes in details J11 and N11.	S107	1
17	Corrected plan keynotes. Revised detail cuts on plan as indicated. Added opening and lintel indication at Stair S-01 & S-02. Corrected detail callout in Section J7.	S108	1
18	Corrected plan keynotes. Revised detail cuts on plan as indicated. Added missing lintel sizes.	S109	1
19	Removed unneeded retaining wall details M1 and M3. Corrected top of foundation wall in detail M9 Corrected slab indication in detail H3. Added reinforcement information to details D16 & J16.	S200	1
20	Corrected topping thickness in detail H1. Corrected detail number at H3. Added 6x6 post to detail H5	S201	1
21	Revised ceiling joist size in details N1, N5 and P10. Revised details D10 & G10 to match architectural details.	S300	1
22	Added hanger to detail K11.	S400	1
23	Outlet locations updated.	E202	1